





BOSCH




Invented for life

When to replace wind- shield wiper blades.





Everything is good!
No action necessary.

No streaking or a maximum of 3 permanent streaks in the outer field of view.



Wiper blades should
be changed within
the next weeks.

One streak in the central field, more than 3 permanent streaks in the outer field of view or several temporary streaks.



Wiper blades need
to be changed
urgently.

Patches of water remaining, chatter marks and haze formation.

Caused by loss of tension of the wiper arm springs; stiff, hard, cracked or dry wiper rubber lip (not used or parked for a long time).

Other reasons: coated windshields, debris or other foreign substances collected either on the glass or blade.

Get a clear view with Bosch Aerotwin.

Find the right Bosch Wiper
www.boschwiperblades.com

